




H1 SMALL COMPRESSION SPRING.  
**MINI DEPTH GAUGE**



HOLES A 10 B 4  
 MATERIAL 16 X 10 STEEL 070M20  
 QTY 1 OFF  
 MAKE A SECOND BASE USING DIMENSIONS IN ( )  
**BASE** 3



MATERIAL 10 DIA. STEEL 230M07  
 QTY 2 OFF  
**SPINDLE** 2



HOLE 4  
 MATERIAL 10 DIA. STEEL 230M07  
 QTY 2 OFF  
 SEE TEXT RE POSITIONING  
 THE HOLE AND LENGTH  
 MAKE HEAD SLIGHTLY CONCAVE.  
**CLAMP** 1