



HARDWARE

H41.	M4 X 16 SOCKET CAP SCREW	2 OFF
H42.	M3 X 10 SOCKET CAP SCREW	2 OFF
H43.	M3 X 12 SOCKET CAP SCREW	1 OFF
H44.	M4 X 25 SOCKET CAP SCREW	2 OFF
H45.	M4 X 16 SOCKET CAP SCREW	4 OFF
H46.	M4 X 6 SOCKET GRUB SCREW	2 OFF
H47.	M4 STEEL WASHER	4 OFF

**FILE CARRIER**

**4**

