



TABLE

6

HARDWARE

H61.	M3 X 10 SOCKET CAP SCREW	4 OFF
H62.	M5 X 16 SOCKET CAP SCREW	2 OFF
H63.	M5 STEEL WASHER	2 OFF



